

## Test Verification of Conformity

**Applicant Name & Address** : Lion TotalCare  
8484 Gulf Freeway  
Houston, TX 77017

**Repair Category Tested** : Outer Shell  
Thermal Liner  
WL Gore RT7100 Moisture Barrier  
WL Gore Crosstech Moisture Barrier  
Stedfast Stedair 3000 Moisture Barrier

**Sample(s) Condition** : Production

**Sample(s) Receive Date** : 04/10/09

**Relevant Standard(s)/Specification(s)** : NFPA 1851 Standard on Selection, Care, and Maintenance of Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting 2008 Edition Section 11

**Verification Issuing Office Name & Address** : Intertek  
3933 US Route 11  
Cortland, NY 13045

**Date of Test(s)** : 04/15/09 through 05/08/09

**Inspection Date(s)** : 05/26/09

**Verification/Report Number(s)** : 3178576CRT-001

On the basis of the tests undertaken, the sample(s) of the above product have been found to comply with the essential requirements of the referenced specifications at the time the tests were carried out.

  
Pam Kavalesky  
Engineer

Date : 06/25/09

**NOTE** : This verification is part of the full test report(s) and should be read in conjunction with it.

This Verification is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Verification. Only the Client is authorized to permit copying or distribution of this Verification. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test/inspection results in referenced from this Verification are relevant only to the sample tested/inspected. This Verification by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.